

COMMISSIONER'S MONTHLY REPORT

Commissioner

Date

May 19

1965

Report for Month of

May

1965

Source and Point of Measurement	Day of the Month															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
I. Boardman Springs																
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)				0.644												
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)				2.7												
#3. Church ditch near to heading				dry												
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)				0.370												
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake				2.72												
II. Thomas Spring																
#5. Above the Olsen house below the tracks				1.89												
III. Drain																
#6. Drain Channel near Railroad Shop and Birmingham properties				0.133												
IV. #8. Levie Ditch - Water to Church Farm, etc.				dry												
V. #9. Pump Water at Church Welfare Farm				dry												

For key to location numbers see drawing P-5107

May 19 - Total Boardman = 3.364 sec ft  
" Total Thomas & North Spgs = 2.3935 sec ft

Submitted by

E. Lewis Allen